

FARM WORKSHOP SAFETY

Serious injury and death from electrocution, crush injury, fire and explosion is occurring in farm workshops. Twenty percent (20%) of farm injury presenting to hospital Emergency Departments is caused by farm maintenance work. More than 30% of these are eye and hand injuries. Whilst these injuries are generally not life threatening, they result in significant downtime, workers compensation claims and reduced farm productivity. The following checklist can be used to help you identify and manage some workshop hazards and safety risks on your farm.

GUARDING

Replacing and maintaining guards on workshop equipment, particularly bench grinders, is one way that farmers can reduce the risk of eye and hand injury to people working in farm workshops.



- Replace bench grinder guards and broken/ pitted spark deflector shields
- Check and replace all power tool guards. Keep them well maintained
- Guard the air compressor belts and pulleys
- Wear eye protection when grinding and using cutting power tools

SAFEGUARDING ELECTRICAL EQUIPMENT

Workshop electrocution is caused by faulty wiring, electrical installation, damaged power leads and water in the workshop.



- Fit a Residual Current Device (RCD) to the electrical circuit board to prevent electrocution
- Routinely test the RCD to check that it is working
- If no RCD is fitted to the electrical circuit board, use a portable RCD
- Check and test all electrical cords and extension leads regularly for wear and damage
- Use a licensed electrician to carry out all electrical work

FARM WORKSHOP SAFETY

MAINTENANCE

Workers and visitors to the workshop are at risk of slip and trip injury if access to the workplace is cluttered. Serious injury and death can be caused being crushed under farm machinery and vehicles during service and maintenance.

- Clean and tidy the workshop. Keep floors free of slip/ trip hazards including oil, tools, extension cords and rubbish
- Support vehicles and machinery with stands before working under jacked vehicles, utes, tractors and machinery
- Inflate split rim tyres in a safety cage
- Store fuel, oil and flammable material away/ outside the workshop from welding and grinding to prevent fire and explosion



PERSONAL PROTECTIVE EQUIPMENT

There is a wide variety of Personal Protective Equipment (PPE) currently on the market to help protect against hazards in the workshop.

- Make sure personal protective equipment (PPE) is available for all work including eye goggles, welding helmet, hearing protection, gloves and work boots
- Wear hearing protection where there is loud noise
- Train and instruct all farm workers to use, store and maintain PPE
- Have a First Aid Kit in the workshop



Farm safety checklists and other information on farm safety risks and controls, can be downloaded from the Farmsafe Australia website at www.farmsafe.org.au.

Australian Centre for Agricultural Health and Safety

PO Box 256 Moree NSW 2400

Ph. (02) 6752 8218 Fax (02) 6752 6639 Email: info@farmsafe.org.au

© Australian Centre for Agricultural Health and Safety 2008